



Vehicle History Report

Report Generated: 04-05-2023
VIN: VF15RE20A55268448

Scan to open report:



Vehicle Specifications

This section lists basic vehicle details encoded by the VIN.

General information

Make	Renault
Model	Clio
Model year	2005
Vehicle class	Subcompact Car
Vehicle type	Passenger car
Manufactured in	France

Manufacturer

Manufacturer	Renault SAS
Adress line 1	13-15 Quai Alphonse Le Gallo
Adress line 2	Boulogne
Region	Europe
Country	France
Note	Manufacturer builds more than 500 vehicles per year

Vehicle specification

Number of doors	3/5
Number of seats	5

AUCTION RECORDS

Title & Condition

Title Type	Clean
Title Description	GB - N Repairable Non Structural
Primary Damage	Front End
Secondary Damage	Minor Dent/scratches
VIN	VF15RE20A55268448

Runs & Drives | Engine Starts | Has Keys

Sale Status

£1,050 GBP
Current Bid

CURRENT
BID

Auction Info

Auction Type	Minimum Bid
Seller Type	Insurance Company
Auction Date	April 6, 2023 6:00 AM CDT
Location	Wolverhampton, United Kingdom

Technical Specs

Odometer :	37,747 actual miles25,453 less than average
Estimated Repair Cost :	£6,646
Avg. Estimated Retail Value :	£6,741
Damage Ratio :	83%
Estimated Winning Bid :	£2,376 - £2,904
Body Style :	Hatchback
Color :	Black
Fuel Type :	Petrol
Transmission :	5 Speed Manual
Drive :	2 Axle Rigid Body

Vehicles Sales History

No previous auction found!



Title Records

This section lists title records.

Type	Description	Date
Clean	GB - N Repairable Non Structural	April 6, 2023 6:00 AM CDT



Accident Records

This section lists accident records from available independent sources.

Type	Damage
Primary Damage	Front End
Secondary Damage	Minor Dent/scratches



Theft Records

This section lists active theft and theft recovery records for this VIN.



No theft or theft recovery records found!



Lien / Impound / Export Records

This section lists lien, impound, and export records (if any).



No records found!



Auction Records

This section lists historical auction listings.



Auction records found!



Sale Records

This section lists historical sale listings from available independent sources.



No sale records found!

Title Checks

This section lists our checks for potential problems related to the title.

Record of Flood Damage?

 No Problems Found!

Record of Fire Damage?

 No Problems Found!

Record of Hail Damage?

 No Problems Found!

Record of Salt Water Damage?

 No Problems Found!

Record of Hail Damage?

 No Problems Found!

Record of Salt Water Damage?

 No Problems Found!

Record of Vandalism?

 No Problems Found!

Record of Kit?

 No Problems Found!

Record of Dismantled?

 No Problems Found!

Record of Junk?

 No Problems Found!

Record of Salvage: Damage or Not Specified?

 No Problems Found!

Record of Test Vehicle?

 No Problems Found!

Record of Refurbished?

 No Problems Found!

Record of Collision?

 No Problems Found!

Record of Salvage Rentention?

 No Problems Found!

Record of Prior Taxi?

 No Problems Found!

Record of Prior Police?

 No Problems Found!

Record of Orignal Taxi?

 No Problems Found!

Record of Orignal Police?

 No Problems Found!

Record of Remanufactured?

 No Problems Found!

Record of Gray Market?

 No Problems Found!

Record of Warranty Return?

 No Problems Found!

Record of Antique?

 No Problems Found!

Record of Classic?

 No Problems Found!

Record of Agricultural Vehicle?

 No Problems Found!

Record of Logging Vehicle?

 No Problems Found!

Record of Street Rod?

 No Problems Found!

Record of Vehicle Contains Reissued VIN?

 No Problems Found!

Record of Replica?

 No Problems Found!

Record of Totaled?

 No Problems Found!

Record of Owner Retained?

 No Problems Found!

Record of Bond Posted?

 No Problems Found!

Record of Memorandum Copy?

 No Problems Found!

Record of Parts Only?

 No Problems Found!

