



# Vehicle History Report

Report Generated: 04-05-2023  
VIN: VF15RE20A55268448

Scan to open report:



## Vehicle Specifications

This section lists basic vehicle details encoded by the VIN.

### General information

Make	Renault
Model	Clio
Vehicle class	Subcompact Car
Vehicle type	Passenger car
Manufactured in	France

### Manufacturer

Manufacturer	Renault SAS
Adress line 1	13-15 Quai Alphonse Le Gallo
Adress line 2	Boulogne
Region	Europe
Country	France
Note	Manufacturer builds more than 500 vehicles per year

### Vehicle specification

Number of doors	3/5
Number of seats	5

## AUCTION RECORDS

Title & Condition

Title Type	Clean
Title Description	GB - N Repairable Non Structural
Primary Damage	Front End
Secondary Damage	Minor Dent/scratches
VIN	VF15RE20A55268448

Runs & Drives | Engine Starts | Has Keys

Sale Status

£1,050 GBP  
Current Bid

CURRENT  
BID

Auction Info

Auction Type	Minimum Bid
Seller Type	Insurance Company
Auction Date	April 6, 2023 6:00 AM CDT
Location	Wolverhampton, United Kingdom

Technical Specs

Odometer :	37,747 actual miles25,453 less than average
Estimated Repair Cost :	£6,646
Avg. Estimated Retail Value :	£6,741
Damage Ratio :	83%
Estimated Winning Bid :	£2,376 - £2,904
Body Style :	Hatchback
Color :	Black
Fuel Type :	Petrol
Transmission :	5 Speed Manual
Drive :	2 Axle Rigid Body

Vehicles Sales History

No previous auction found!



Title Records

This section lists title records.

Type	Description	Date
Clean	GB - N Repairable Non Structural	April 6, 2023 6:00 AM CDT



## Accident Records

This section lists accident records from available independent sources.

Type	Damage
Primary Damage	Front End
Secondary Damage	Minor Dent/scratches



## Theft Records

This section lists active theft and theft recovery records for this VIN.



No theft or theft recovery records found!



## Lien / Impound / Export Records

This section lists lien, impound, and export records (if any).



No records found!



## Auction Records

This section lists historical auction listings.



Auction records found!



## Sale Records

This section lists historical sale listings from available independent sources.



No sale records found!

## Title Checks

This section lists our checks for potential problems related to the title.

### Record of Flood Damage?

 No Problems Found!

### Record of Fire Damage?

 No Problems Found!

### Record of Hail Damage?

 No Problems Found!

### Record of Salt Water Damage?

 No Problems Found!

### Record of Hail Damage?

 No Problems Found!

### Record of Salt Water Damage?

 No Problems Found!

### Record of Vandalism?

 No Problems Found!

### Record of Kit?

 No Problems Found!

### Record of Dismantled?

 No Problems Found!

### Record of Junk?

 No Problems Found!

### Record of Salvage: Damage or Not Specified?

 No Problems Found!

### Record of Test Vehicle?

 No Problems Found!

### Record of Refurbished?

 No Problems Found!

### Record of Collision?

 No Problems Found!

### Record of Salvage Rentention?

 No Problems Found!


### Record of Prior Taxi?

 No Problems Found!

### Record of Prior Police?

 No Problems Found!

### Record of Orignal Taxi?

 No Problems Found!

### Record of Orignal Police?

 No Problems Found!

### Record of Remanufactured?

 No Problems Found!

### Record of Gray Market?

 No Problems Found!

### Record of Warranty Return?

 No Problems Found!

### Record of Antique?

 No Problems Found!

### Record of Classic?

 No Problems Found!

### Record of Agricultural Vehicle?

 No Problems Found!

### Record of Logging Vehicle?

 No Problems Found!

### Record of Street Rod?

 No Problems Found!

### Record of Vehicle Contains Reissued VIN?

 No Problems Found!

### Record of Replica?

 No Problems Found!

### Record of Totaled?

 No Problems Found!


### Record of Owner Retained?

 No Problems Found!

### Record of Bond Posted?

 No Problems Found!

### Record of Memorandum Copy?

 No Problems Found!

### Record of Parts Only?

 No Problems Found!

