



Vehicle History Report

Report Generated: 04-05-2023
VIN: W0LBF6EC0HG162855

Scan to open report:



Vehicle Specifications

This section lists basic vehicle details encoded by the VIN.

General information

Make	Vauxhall
Model	ASTRA-K
Fuel type	Gasoline
Transmission	Manual
Manufactured in	Germany

Manufacturer

Manufacturer	Adam Opel AG
Adress line 1	Bahnhofplatz
Adress line 2	65423 Russelsheim
Region	Europe
Country	Germany
Note	Manufacturer builds more than 500 vehicles per year

Vehicle specification

Manual gearbox	MT
Fuel type	Gasoline
Emission standard	EEC 14

AUCTION RECORDS

Title & Condition

Title Type	Clean
Title Description	GB - Stolen/Recovered Minimal Dmg
Primary Damage	Minor Dent/scratches
Secondary Damage	Normal Wear
VIN	W0LBF6EC0HG162855

Runs & Drives | Engine Starts | Has Keys

Sale Status

£5,000 GBP Sold

SOLD

Auction Info

Seller Type	Insurance Company
Auction Date	May 26, 2020 6:00 AM CDT
Location	Deeside, United Kingdom
Buyer Country	United Kingdom

Technical Specs

Avg. Estimated Retail Value :	£11,379
Estimated Winning Bid :	£4,940 - £7,410
Color :	Black
Fuel Type :	Petrol
Transmission :	6 Speed Manual
Drive :	2 Axle Rigid Body

Vehicles Sales History

in 18 hours	Lot relisted
2 years ago	Sold (This listing)

AUCTION RECORDS

Title & Condition

Title Type	Clean
Title Description	GB - Cat D - Salvage
Primary Damage	Minor Dent/scratches
Secondary Damage	All Over
VIN	W0LBF6EC0HG162855

Runs & Drives | Engine Starts | Has Keys

Sale Status

Unknown Sale
Info Unknown Sale Info

UNKNOWN
SALE INFO

Technical Specs

Odometer :	20,310 actual miles13,427 less than average
Avg. Estimated Retail Value :	£11,379
Estimated Winning Bid :	£4,940 - £7,410
Color :	Black
Engine Type :	1399. CC
Fuel Type :	Petrol
Transmission :	6 Speed Manual
Drive :	2 Axle Rigid Body

Auction Info

Auction Type	Minimum Bid
Seller Type	Third Party
Auction Date	January 18, 2021 11:00 AM CST
Location	Sandy, United Kingdom
Buyer Country	United Kingdom

Vehicles Sales History

Jan 11, 2021	Seller declined £4,450 GBP
Jan 4, 2021	Seller declined £5,200 GBP
in 18 hours	Lot relisted
2 years ago	Lot sold for £5,000

AUCTION RECORDS

Title & Condition

Title Type	Clean
Title Description	GB - S Repairable Structural
Primary Damage	Rear End
Secondary Damage	All Over
VIN	W0LBF6EC0HG162855

Runs & Drives | Engine Starts | Has Keys

Sale Status

£275 GBP Current Bid

CURRENT
BID

Auction Info

Auction Type	Minimum Bid
Seller Type	Insurance Company
Auction Date	April 6, 2023 6:00 AM CDT
Location	Rochford, United Kingdom

Technical Specs

Odometer :	42,935 miles on title
Estimated Repair Cost :	£11,286
Avg. Estimated Retail Value :	£9,212
Damage Ratio :	138%
Estimated Winning Bid :	£1,612 - £1,970
Body Style :	Hatchback
Color :	Black
Fuel Type :	Petrol
Transmission :	6 Speed Manual
Drive :	2 Axle Rigid Body

Vehicles Sales History

in 18 hours	Relisted (This listing)
2 years ago	Lot sold for £5,000



Title Records

This section lists title records.

Type	Description	Date
Clean	GB - Stolen/Recovered Minimal Dmg	May 26, 2020 6:00 AM CDT
Clean	GB - Cat D - Salvage	January 18, 2021 11:00 AM CST

Type	Description	Date
Clean	GB - S Repairable Structural	April 6, 2023 6:00 AM CDT



Accident Records

This section lists accident records from available independent sources.

Type	Damage
Primary Damage	Minor Dent/scratches
Secondary Damage	Normal Wear
Primary Damage	Minor Dent/scratches
Secondary Damage	All Over
Primary Damage	Rear End
Secondary Damage	All Over



Theft Records

This section lists active theft and theft recovery records for this VIN.



No theft or theft recovery records found!



Lien / Impound / Export Records

This section lists lien, impound, and export records (if any).



No records found!



Auction Records

This section lists historical auction listings.



Auction records found!



Sale Records

This section lists historical sale listings from available independent sources.

Date	Details
in 18 hours	Relisted (This listing)
2 years ago	Lot sold for £5,000

Title Checks

This section lists our checks for potential problems related to the title.

Record of Flood Damage?

No Problems Found!

Record of Fire Damage?

No Problems Found!

Record of Hail Damage?

No Problems Found!

Record of Salt Water Damage?

No Problems Found!

Record of Hail Damage?

No Problems Found!

Record of Salt Water Damage?

No Problems Found!

Record of Vandalism?

No Problems Found!

Record of Kit?

No Problems Found!

Record of Dismantled?

No Problems Found!

Record of Junk?

No Problems Found!

Record of Salvage: Damage or Not Specified?

No Problems Found!

Record of Test Vehicle?

No Problems Found!

Record of Refurbished?

No Problems Found!

Record of Collision?

No Problems Found!

Record of Salvage Retention?

No Problems Found!

Record of Prior Taxi?

No Problems Found!

Record of Prior Police?

No Problems Found!

Record of Original Taxi?

No Problems Found!

Record of Original Police?

No Problems Found!

Record of Remanufactured?

No Problems Found!

Record of Gray Market?

No Problems Found!

Record of Warranty Return?

No Problems Found!

Record of Antique?

No Problems Found!

Record of Classic?

No Problems Found!

Record of Agricultural Vehicle?

No Problems Found!

Record of Logging Vehicle?

No Problems Found!

Record of Street Rod?

 No Problems Found!

Record of Vehicle Contains Reissued VIN?

 No Problems Found!

Record of Replica?

 No Problems Found!

Record of Totaled?

 No Problems Found!

Record of Owner Retained?

 No Problems Found!

Record of Bond Posted?

 No Problems Found!

Record of Memorandum Copy?

 No Problems Found!

Record of Parts Only?

 No Problems Found!

Record of Recovered Theft?

 No Problems Found!

Record of Undisclosed Lien?

 No Problems Found!

Record of Prior Owner Retained?

 No Problems Found!

Record of Non-confirmity Uncorrected?

 No Problems Found!

Record of Non-confirmity Corrected?

 No Problems Found!

Record of Safety Defect Uncorrected?

 No Problems Found!

Record of Safety Defect Corrected?

 No Problems Found!

Record of VIN Replaced?

 No Problems Found!

Record of Gray Market: Non-Complaint?

 No Problems Found!

Record of Gray Market: Complaint?

 No Problems Found!

Record of Manufacturer Buyback?

 No Problems Found!

Record of Former Rental?

 No Problems Found!

Record of Salvage: Stolen?

 No Problems Found!

Record of Salvage: Reasons Other than Damage or Stolen?

 No Problems Found!

Record of Disclosed Damage?

 No Problems Found!


Record of Prior Non-Repairable/ Repaired?

 No Problems Found!

Record of Crushed?

 No Problems Found!

Record of Hazardous?

 No Problems Found!

Record of Export Only Vehicle?

 No Problems Found!

Record of Odometer: Actual?

 No Problems Found!


Record of Odometer: Non-Actual?

 No Problems Found!


Record of Odometer: Tampering Verified?

 No Problems Found!

Record of Odometer: Exempt from Odometer Disclosure?

 No Problems Found!

Record of Odometer: Exceeds Mechanical Limits?

 No Problems Found!


Record of Odometer: May be Altered?

 No Problems Found!

Record of Odometer: Replaced?

 No Problems Found!

Record of Odometer: Reading at Time of Renewal?

 No Problems Found!

Record of Odometer: Discrepancy?

 No Problems Found!

Record of Odometer: Call Title Division?

 No Problems Found!

Record of Odometer: Exceeds Mechanical Limits Rectified?

 No Problems Found!

This Vehicle History Report - EU Report is based only on information acquirable by Vehicle History Report - EU as at the time of generating this report. Note that other information about this vehicle, including problems and services, may not have been reported to Vehicle History Report - EU. You are strongly advised to use this report only as an additional but important tool, along with the vehicle inspection and test drive, to make an informed decision about the purchase of this vehicle. © 2022 [Vehicle History Report - EU](#). All Rights Reserved.